

15

PART A TECHNICAL REVIEW CHECKLIST

I. EPA I.D. NUMBER IAD000610436

II. FACILITY NAME AND LOCATION Amana Refrigeration Inc, Middle,
Iowa, 52307

III. APPLICATION FILE CHECKED OUT BY THOMAS JANSZEN
ON 4/30/82

IV. TECHNICAL REVIEW INFORMATION (122.24)

REVIEW ITEMS	OK	NOT OK	REMARKS
1. Administrative Items Complete	X		
2. Latitude & Longitude of Facility	X		
3. Name, Address and Telephone Number of Owner of Facility	X		
4. New Facility _____ Exist. Facility <u>X</u> First App. <u>X</u> Revised App. _____	X		
5. Description and Design Capacity of TSD Processes	X		
6. Info. on wastes listed in Part 261 to be treated, stored or disposed of at the facility.		X	see remarks on back of sheet
7. Check design capacity against estimated annual quantity for reasonableness		X	see back of sheet
8. Facility Drawing <u>X</u> Map <u>X</u> Photographs <u>X</u>	X		
9. Additional comments (incompatible wastes, inconsistencies, etc.)			



6. \checkmark FO17, FO18, and U229 deleted

\checkmark U002, U184, D001, D003 in notification but not Part 'A'

7 SOI design = 42,900 gal

SOI actual \approx 405,066 assuming 7.5 lb/gal

VII. CERTIFICATION OF REVIEW

The facility permit application and supporting information has been reviewed in accordance with applicable RCRA Regulations, 40 CFR Parts 260-267 and 122-124.

Permits Work Unit Reviewer

Date

Permits Work Unit Supervisor

Date

VIII. File returned to CSC on _____